



GHENT MANUFACTURING, INC.
REPLACEMENT LETTER BREAKDOWN - COUNT & TYPE

Jul-08

	A	B	C	D	E	F	G	H	I	J	K	L	M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z
LH12	14	6	8	8	14	6	6	6	12	4	4	10	8	10	14	8	4	12	12	12	8	4	4	4	6	4
LH34	14	6	8	8	14	6	6	6	12	4	4	10	8	10	14	8	4	12	12	12	8	4	4	4	6	4
LH1	14	6	8	8	14	6	6	6	12	4	4	10	8	10	14	8	4	12	12	12	8	4	4	4	6	4
LG34	15	9	9	9	21	9	9	9	12	3	6	9	9	9	21	9	3	12	15	12	9	6	9	3	6	3
LG12	15	9	9	9	21	9	9	9	12	3	6	9	9	9	21	9	3	12	15	12	9	6	9	3	6	3
LG1-12	15	9	9	9	21	9	9	9	12	3	6	9	9	9	21	9	3	12	15	12	9	6	9	3	6	3
LG1	15	9	9	9	21	9	9	9	12	3	6	9	9	9	21	9	3	12	15	12	9	6	9	3	6	3

	0	1	2	3	4	5	6	7	8	9	&	C	,	-	.	\$	*	→	/	Ñ	☆
LH12	4	6	4	4	4	4	4	4	4	4	2	2	6	8	6	4	6	2			
LH34	4	6	4	4	4	4	4	4	4	4	2	2	6	8	6	4	6	2			
LH1	4	6	4	4	4	4	4	4	4	4	2	2	6	8	6	4		2		2	6
LG34		6	6	6	6	6	6	6	6	6	3	3	3	3	6	6			3		
LG12		4	6	6	6	6	6	6	6	6	3	3	3	3	6	6			2		
LG1-12		2	6	6	6	6	6	6	6	6	3	3	3	3	6	6			3		
LG1		4	6	6	6	6	6	6	6	6	3	3	3	3	6				3		

	TOTALS	SPRUES/PACK
LH12	286	2 sprues/pack
LH34	286	2 sprues/pack
LH1	288	2 sprues/pack
LG34	327	3 sprues/pack
LG12	324	3 sprues/pack
LG1-12	324	6 sprues/pack
LG1	324	6 sprues/pack